BHP BILLITON PLC Form 6-K October 25, 2005

UNITED STATES SECURITIES AND EXCHANGE COMMISSION Washington, D.C. 20549

Form 6-K

REPORT OF FOREIGN PRIVATE ISSUER PURSUANT TO RULE 13a-16 OR 15d-16 UNDER THE SECURITIES EXCHANGE ACT OF 1934

October

13, 2005

BHP Billiton

Plc

(Translation of registrant's name into English) Neathouse Place London SW1V 1BH United Kingdom (Address of principal executive office) Indicate by check mark whether the registrant files or will file annual reports under cover of Form 20-F or Form 40-F: [x] Form 20-F [] Form 40-F
Indicate by check mark if the registrant is submitting the Form 6-K in paper as permitted by Regulation S-T Rule 101(b)(1): []
Indicate by check mark if the registrant is submitting the Form 6-K in paper as permitted by Regulation S-T Rule 101(b)(7): []
Indicate by check mark whether the registrant by furnishing the information contained in this Form is also thereby furnishing the information to the Commission pursuant to Rule 12g3-2(b) under the Securities Exchange Act of 1934: $[\]$ Yes $[\ x]$ No
If "Yes" is marked, indicate below the file number assigned to the registrant in connection with Rule 12g3-2(b): $\frac{n/a}{}$

13 October 2005 Number 39/05

BHP BILLITON UPDATE ON US GULF OF MEXICO OPERATIONS

Edgar Filing: BHP BILLITON PLC - Form 6-K

BHP Billiton's petroleum exploration and production operations in the US Gulf of Mexico (GoM) have recommenced following Hurricane Rita. After completing necessary inspections, both the Mad Dog and Genesis fields have safely resumed production. The West Cameron 76, Starlifter, Green Canyon 18-Ewing Bank 988, and Green Canyon 60 fields are in various stages of start-up and are expected to resume in the next few days and weeks. This schedule is dependent on the resumption of third-party downstream infrastructure, including pipelines, onshore terminals and other facilities.

BHP Billiton's share of production from the GoM for the 12-month period ended June 30, 2005 was approximately 25,000 barrels of oil equivalent per day (boe/d). As of October 10, the company's production level had returned to about forty percent of this rate.

As previously disclosed, the Typhoon facility was heavily damaged by Hurricane Rita. The timing of production resumption from the Typhoon and Boris oil and gas fields is unclear. For the 12-month period ending June 30, 2005, 4.3 million barrels of oil and 7.1 billion cubic feet of natural gas were produced through the Typhoon facility (BHP Billiton share: equivalent to approximately 15,000 boe/d). In the current financial year, production through Typhoon was expected to be less than 5 percent of the company's total oil and gas production.

The operator of the Typhoon field (Chevron) has formed two teams; an investigation team has been charged with determining why the facility was lost and a restoration team will recommend how best to restore Typhoon-Boris production. It is too early to speculate on the findings and recommendations from either team. We expect the investigation team to take several weeks and the restoration team to take several months to complete their work.

The company holds both property damage and business interruption insurance in relation to the assets in the GoM. The likely recovery from insurance is not known at this stage.

Among other activities, the company's GoM exploration and development drilling operations have resumed. As a result of Hurricanes Katrina and Rita, all well schedules have been delayed by 4-6 weeks. The effect that these delays will have on production in future years is difficult to assess at this time.

The company does not currently see any impact on the first-oil schedules for its Atlantis or Neptune developments. The Atlantis field is the next BHP Billiton development to come on-stream. This is still anticipated during the third quarter of 2006. However, flow-on effects from further delays with third-party service providers to other projects or unusually severe marine conditions over the next 12 months cannot be ruled out.

For the current financial year, BHP Billiton's net oil and gas production is likely to be as much as 10 million boe lower than previous guidance. Approximately 4.5 million boe of this is associated with GoM operations, which assumes loss of production from Typhoon for the balance of the fiscal year. Unplanned outages in Australia account for 1.5 million boe of lower production. The balance relates to our Production Sharing and Risk Sharing Contracts, whereby increasing oil prices reduce the company's production share.

Further information on BHP Billiton can be found on our Internet site: h	nttp://www.bhpbilliton.com
--	----------------------------

Australia United Kingdom

Edgar Filing: BHP BILLITON PLC - Form 6-K

Jane Belcher, Investor Relations

Tel: +61 3 9609 3952 Mobile: +61 417 031 653 email: Jane.H.Belcher@bhpbilliton.com

Mark Lidiard, Investor & Media Relations Tel: +44 20 7802 4156 Mobile: +44 7769 934 942

email: Mark.Lidiard@bhpbilliton.com

Tania Price, Media Relations

Tel: +61 3 9609 3815 Mobile: +61 419 152 780

email: Tania.Price@bhpbilliton.com

Ariane Gentil, Media Relations

Tel: +44 20 7802 4177 Mobile: +44 78 81 51 8715

email: Ariane.Gentil@bhpbilliton.com

United States

Tracey Whitehead, Investor & Media Relations Tel: US +1 713 599 6100 or UK +44 20 7802 4031

Mobile: +44 7917 648 093

email: Tracey.Whitehead@bhpbilliton.com

South Africa

Michael Campbell, Investor & Media Relations Tel: +27 11 376 3360 Mobile: +27 82 458 2587 email: Michael.J.Campbell@bhpbilliton.com

BHP Billiton Limited ABN 49 004 028 077

BHP Billiton Plc Registration number 3196209

Registered in Australia

Registered Office: Level 27, 180 Lonsdale Street Melbourne Victoria

3000

Telephone +61 1300 554 757 Facsimile +61 3 9609 3015

Registered in England and Wales

Registered Office: Neathouse Place London SW1V 1BH United

Kingdon

Telephone +44 20 7802 4000 Facsimile +44 20 7802 4111

The BHP Billiton Group is headquartered in Australia

Edgar Filing: BHP BILLITON PLC - Form 6-K

SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

BHP Billiton Plc

Date: 13 October 2005 By: Karen Wood

Name: Karen Wood

Title: Company Secretary